TERMITE MONITORING AND REINSPECTION REPORT

Street address	City	State / ZIP	Date of visit	Pages
541 Forest Hills Drive	Roswell	GA 30075	09/15/2026	1

PT

Peachtree Termite & Pest Control

1480 Roswell Road, Suite 200
Marietta, GA 30062
(770) 555-0148
office@peachtreetermite.com

License no. 128419
Contract no. B-23-0917
Report no. 26-2214

Property owner	Mailing address
Harold Pruitt	541 Forest Hills Drive, Roswell, GA 30075

Contract

Control measure	Installed or first treated	Coverage	Renewed through
Baiting system (Sentricon)	09/14/2023	Retreatment and repair	09/13/2027

This visit

☑ Inspection or reinspection ☑ Bait station monitoring

Performed by	Registration or certification no.	Structure(s) inspected
Travis Coker	RE-38472	House and attached garage

Wood destroying organisms or signs of termite activity

In or on the structure ☐ Found ☑ Not found

In bait or monitoring stations ☑ Found ☐ Not found ☐ No stations

What was found, and where

Live subterranean termites feeding in station 9, back yard, 4 ft left of the deck stairs. About half the bait was eaten. No termites, mud tubes, or new damage on the house or garage.

Conducive conditions

Landscape timbers touch the siding at the left front corner, and the mulch there is piled over the top of the foundation. Advised pulling both back 6 in.

Areas not inspected, and why

Finished basement walls and floor, behind drywall and carpet. Garage left wall, behind stored boxes.

Bait and monitoring stations

Station	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Result	N	N	N	N	N	N	N	N	A, R	N	N	N	N	X	N
Station	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
Result	N	N	N	N	N	R	R								

N No activity **A** Termite activity **R** Bait added or replaced **D** Damaged, replaced **X** Not monitored

Stations not monitored, and why	Stations added this visit	Stations in place now
14: under the new paver patio at the back door, no access.	21 and 22, at the patio's outer edge	21 (station 14 abandoned)

Action taken

☐ None needed ☑ Bait added or replaced ☐ Spot treatment

Product	EPA Reg. No.	Amount, and where	Areas of active infestation, last 5 years
Recruit HD termite bait (noviflumuron 0.5%)	62719-608	3 bait devices: 1 in station 9, 1 each in stations 21 and 22	0

Signature of person who did the visit	Date	Next visit due
Travis Coker	09/15/2026	09/14/2027, within 30 days

Rule 620-6-.02(5): "In addition to all other recordkeeping requirements, the licensee shall maintain reports of all monitoring, inspections and/or reinspections of the structure(s), baits or baiting systems and devices under contract. Such reports shall be provided to the property owner and a copy shall be maintained by the licensee for inspection by the enforcement agency, in a reasonable amount of time, for a period of two (2) years. The reports shall include the date of the monitoring, inspection or reinspection, name of the person performing the monitoring, inspection or reinspection and whether or not Wood Destroying Organisms or signs of termite activity were found."