STRUCTURAL FUMIGATION REPORT AND LOG

Street address	City	State / ZIP	Date of fumigation	Pages
1802 Sealy Avenue	Galveston	TX 77550	10/20/2026	2

GC

Gulf Coast Fumigation
3920 Broadway Street
Galveston, TX 77550
(409) 555-0159
dispatch@gulfcoastfumigation.com

Report GCF-26-0417
TPCL No. 0752390
County Galveston

Property owner	**Owner's address**
Patricia and Glenn Hartwell	1802 Sealy Avenue, Galveston, TX 77550
Structure type (B)	**Target pest(s) (B)**
Two-story wood-frame house, pier and beam, built 1899	Drywood termites (Incisitermes snyderi)

Certified applicator responsible for the fumigation and providing direct on-site supervision	**License No.**
Curtis Boudreaux	0726817

Dosing calculations

Measured cubic feet fumigated (B)	Dosage factor	Hours of exposure	Temperature (°F)	Wind (mph)
46,800 cu ft (46.8 MCF)	1X	20	74, soil	8, from the SE

Tarp condition	Under seal type	Seal condition	Underseal
Good	Crawlspace (pier and beam)	Good	Sandy soil, wetted

(B) Write down before the fumigation starts, as the fumigant label requires. The company and site address above are (B) items too.

Notices and site safety

TDA notified (date)	Time	Proof of notification
10/19/2026	4:12 p.m.	TDA confirmation email saved to the job file

Fire, police, or emergency authority	Agency	Person informed	How	Date	Time
Before introduction	Galveston Fire Department	Lauren Mireles, dispatch	Phone	10/20/2026	11:20 a.m.
Released for occupancy	Galveston Fire Department	Tomás Garza, dispatch	Phone	10/22/2026	9:30 a.m.

- [x] Fumigant fact sheet given to occupant
- [x] Occupants out and vacancy checked
- [x] Flames and pilot lights out
- [x] Tarp holes and tears taped or repaired
- [x] Warning signs posted at all entrances
- [x] Secondary locks on all entrances
- [x] Keys to secondary locks on hand
- [x] Two working SCBAs on site

Guard posted	**Extraordinary safety precautions taken**
Raymond Landry, 6:00 p.m. to 7:00 a.m., checked hourly	Tenant of the rear garage apartment, 12 ft from the tarp, stayed away until release. Sand snakes doubled on the windward south side.

Fumigant introduction			
Fumigant used Vikane Gas Fumigant (sulfuryl fluoride)	**EPA Reg. No.** 1015-78	**Pounds of fumigant applied** 24 lb (8.2 oz per MCF)	**Cylinder serial number(s)** A417726 (9 lb), A422309 (15 lb)
Warning agent Chloropicrin	**Total ounces introduced** 4 fl oz	**Number of introduction sites** 2	

	Fumigant release	Aeration initiated	Final clearance testing completed	Released for occupancy
Date	10/20/2026	10/21/2026	10/22/2026	10/22/2026
Time	12:45 p.m.	9:00 a.m.	9:10 a.m.	9:20 a.m.
Certified applicator	Curtis Boudreaux	Curtis Boudreaux	Curtis Boudreaux	Curtis Boudreaux
License No.	0726817	0726817	0726817	0726817
Signature	Curtis Boudreaux	Curtis Boudreaux	Curtis Boudreaux	Curtis Boudreaux
Persons assisting (name and license No.)	Andre Fontenot, 0761244	Andre Fontenot, 0761244; Luis Castañeda, 0774518	None	

Clearance device model	Serial No.	Last calibrated	Calibrated by
Spectros SF-ExplorIR Plus	SXP-21486	03/12/2026	Spectros Instruments

Final clearance readings where people stand, sit, or lie down (1 ppm or less)

Room	ppm	Room	ppm	Room	ppm
Living room	0.0	Dining room	0.0	Kitchen	0.5
Den	0.0	Primary bedroom	0.0	Bedroom 2	0.5
Bedroom 3	0.0	Upstairs hall closet	0.5	Upstairs bath	0.0

Sticker posted ☑ Next to the electric breaker box ☐ Next to the water heater ☐ Beneath the kitchen sink

Emergency response information	
Get exposed person to fresh air. Call 911 or an ambulance. Keep exposed person warm and at rest. Make sure person can breathe freely. If breathing has stopped, give artificial respiration. Do not put anything in the mouth of an unconscious person.	**Nearest hospital** UTMB Galveston emergency department, 301 University Blvd.

Comments

Upstairs hall closet first read 1.5 ppm at 8:50 a.m. Opened the closet and hall windows and ran a fan, then reread 0.5 ppm at 9:05 a.m. Owners got the Vikane fact sheet with the contract on 10/12/2026.

4 TAC §7.178(l): "…the business performing the structural fumigation shall compile and retain a report for each fumigation job and/or treatment for a period of at least two (2) years. The certified applicator responsible for the fumigation must have a copy of the report at the time of the fumigation."