4-Point Inspection Form

Based on Citizens sample form Insp4pt 03 25

Insured/Applicant Name: Luis and Andrea Navarro

Application / Policy #: Pending

Address Inspected: 4115 West Bay Court Avenue, Tampa, FL 33611

Actual Year Built: 1994

Date Inspected: 08/19/2026

Minimum Photo Requirements:

- [x] Dwelling: Each side
- [x] Roof: Each slope
- [x] Plumbing: Water heater (incl TPRV), under cabinet plumbing/drains, exposed valves
- [x] Main electrical service panel with interior door label
- [x] Electrical box with panel off
- [x] **All** hazards or deficiencies noted in this report

A Florida-licensed inspector must complete, sign and date this form.

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System

Separate documentation of any single strand aluminum wiring remediation must be provided and certified by a licensed electrician.

Main Panel

Type: [x] Circuit breaker [ ] Fuse

Total Amps: 200

Is amperage sufficient for current usage? [x] Yes [ ] No (explain)

Second Panel

Type: [ ] Circuit breaker [ ] Fuse

Total Amps: N/A

Is amperage sufficient for current usage? [ ] Yes [ ] No (explain)

Indicate presence of any of the following:

- [ ] Cloth wiring
- [ ] Active knob and tube
- [ ] Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): _____

* If single strand (aluminum branch) wiring, provide details of all remediation. *Separate documentation of all work must be provided.*

- [ ] Connections repaired via COPALUM crimp
- [ ] Connections repaired via AlumiConn

Hazards Present

- [ ] Blowing fuses
- [ ] Tripping breakers
- [ ] Empty sockets
- [ ] Loose wiring
- [ ] Improper grounding
- [ ] Corrosion
- [ ] Over fusing
- [ ] Double taps
- [ ] Exposed wiring
- [ ] Unsafe wiring
- [ ] Improper breaker size
- [ ] Scorching
- [ ] Other (explain)

General condition of the electrical system: [x] Satisfactory [ ] Unsatisfactory **(explain)**

Supplemental information

Main Panel

Panel age: 11 years

Year last updated: 2015

Brand/Model: Square D Homeline

Second Panel

Panel age: N/A

Year last updated: _____

Brand/Model: _____

Wiring Type(s)

- [x] Copper
- [ ] Single Strand AL
- [ ] Multistrand AL
- [ ] Copper Clad AL
- [ ] Cloth (Knob & Tube)
- [ ] Cloth Jacket Rubber Insulated
- [x] NM, BX or Conduit
- [ ] Other

4-Point Inspection Form

HVAC System

Central AC: ☑ Yes ☐ No

Central heat: ☑ Yes ☐ No

If not central heat, indicate **primary** heat source and fuel type: _____

Are the heating, ventilation and air conditioning systems in good working order? ☑ Yes ☐ No (explain) _____

Date of last HVAC servicing/inspection: 05/14/2026

Hazards Present

Is a wood-burning stove or central gas fireplace present? ☐ Yes ☑ No Was it professionally installed? ☐ Yes ☐ No

Space heater used as primary heat source? ☐ Yes ☑ No

Is the source portable? ☐ Yes ☐ No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?

☐ Yes ☑ No

Supplemental Information

Age of system: 6 years

Year last updated: 2020

(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

Plumbing System

Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No

Is there any indication of an active leak? ☐ Yes ☑ No

Is there any indication of a prior leak? ☑ Yes ☐ No

Water heater location: Garage

General condition of the following plumbing fixtures and connections to appliances:

	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	☑	☐	☐	Toilets	☑	☐	☐
Refrigerator	☑	☐	☐	Sinks	☑	☐	☐
Washing machine	☑	☐	☐	Sump pump	☐	☐	☑
Water heater	☑	☐	☐	Main shut off valve	☑	☐	☐
Showers/Tubs	☑	☐	☐	All other visible	☑	☐	☐

If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).

Supplemental Information

Age of Piping Supply System:

_____ Original to home

X Completely re-piped

_____ Partially re-piped

Age of Piping Drain System:

X Original to home

_____ Completely re-piped

_____ Partially re-piped

Age of water heater 7 years (2019)

(Provide year and extent of renovation in the comments below)

Type of pipes (check all that apply)

☐ Copper

☑ PVC/CPVC

☐ Galvanized

☐ Cast Iron

☐ Polybutylene

☐ ABS

☑ PEX Year Installed: 2012

☐ Other (specify) _____

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the *Roof Inspection Form*.)

Predominant Roof

Covering material: Architectural asphalt shingle
Roof age (years): 9
Remaining useful life (years): 11
Date of last roofing permit: 03/14/2017
Date of last update: 04/27/2017

If updated (check one):
- [x] Full replacement
- [ ] Partial replacement
  % of replacement: 100%

Overall condition:
- [x] Satisfactory
- [ ] Unsatisfactory **(explain below)**

Any visible signs of damage / deterioration?
(check all that apply and explain below)
- [ ] Cracking
- [ ] Cupping/curling
- [ ] Excessive granule loss
- [ ] Exposed asphalt
- [ ] Exposed felt
- [ ] Missing/loose/cracked tabs or tiles
- [ ] Soft spots in decking
- [ ] Visible hail damage

Any visible signs of leaks? [ ] Yes [x] No (If "yes" explain below)
Attic/underside of decking [ ] Yes [x] No
Interior ceilings [ ] Yes [x] No

Secondary Roof

Covering material: None
Roof age (years): _____
Remaining useful life (years): _____
Date of last roofing permit: _____
Date of last update: _____

If updated (check one):
- [ ] Full replacement
- [ ] Partial replacement
  % of replacement: _____

Overall condition:
- [ ] Satisfactory
- [ ] Unsatisfactory **(explain below)**

Any visible signs of damage / deterioration?
(check all that apply and explain below)
- [ ] Cracking
- [ ] Cupping/curling
- [ ] Excessive granule loss
- [ ] Exposed asphalt
- [ ] Exposed felt
- [ ] Missing/loose/cracked tabs or tiles
- [ ] Soft spots in decking
- [ ] Visible hail damage

Any visible signs of leaks? [ ] Yes [ ] No (If "yes" explain below)
Attic/underside of decking [ ] Yes [ ] No
Interior ceilings [ ] Yes [ ] No

Additional Comments/Observations (use additional pages if needed):

Electrical: Main panel and 200-amp service replaced in 2015 (Square D Homeline), per the seller and City of Tampa permit history. Copper NM-B branch wiring throughout. No aluminum, cloth, or knob and tube wiring. No second panel.

HVAC: Carrier 3-ton split heat pump with electric heat strips, condenser data plate dated 03/2020. Heating and cooling both ran normally. Service sticker on the air handler dated 05/14/2026.

Plumbing: Whole-house supply re-piped in PEX in 2012, replacing the original polybutylene. None seen at the water heater, under the sinks, or at the main shut off valve. Drains are original PVC. Rheem 50-gallon electric water heater in the garage, data plate dated 06/2019, with its TPR valve piped to the exterior.

Prior leak: dry stain on the kitchen sink cabinet floor from a supply line the seller replaced. The cabinet floor is firm and dry, and the moisture meter read normal. No active leaks.

Roof: Whole roof re-roofed in architectural asphalt shingles under a City of Tampa permit applied for 03/14/2017 and finaled 04/27/2017. No secondary roof. Normal wear for its age. No damage, and no leaks seen in the attic or at the ceilings. Photos of each slope attached.

All *4-Point Inspection Forms* must be completed and signed by a verifiable Florida-licensed inspector.
I certify that the above statements are true and correct.

Inspector Signature	Title	License Number	Date
Jenna Albrecht	Owner and Inspector	HI12547	08/19/2026

Company Name	License Type	Work Phone
Bayshore Home Inspections, LLC	Home Inspector	(813) 555-0175

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each *4-Point Inspection Form*. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- **All** hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the *4-Point Inspection Form* must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.