# Colorado septic transfer inspection worksheet

5 CCR 1002-43, section 43.4.L

| Owner and property | |
|---|---|
| **Owner name**<br>Harold and June Kessler | **Owner phone**<br>(303) 555-0119 |
| **Property address**<br>5470 N 79th St, Longmont, CO 80503 | |
| **Legal description**<br>Lot 4, Block 2, Prairie Ridge Subdivision | |

| Inspector | |
|---|---|
| **Inspector name**<br>Dana Whitcomb | **NAWT number**<br>NAWT 18842 |
| **Inspection date**<br>April 21, 2026 | **Time**<br>10:30 AM |

**System components**

| Component | Type | Size or capacity | Condition |
|---|---|---|---|
| Septic tank | Concrete, two compartment | 1,250 gal | Outlet baffle cracked |
| Soil treatment area | Gravel trenches, 4 laterals | About 900 sq ft | No ponding or surfacing |
| | | | |

| Records from last 12 months | |
|---|---|
| **Tank pumped**<br>April 20, 2026 | **Pumping receipt**<br>Flatirons Septic Pumping #40917 |
| **Mechanical report**<br>No mechanical parts | **Soil treatment report**<br>Included in this inspection |

| Findings | |
|---|---|
| **Parts not working**<br>Outlet baffle cracked; needs replacement | |
| **Well setback**<br>Well 112 ft from soil treatment area; meets setback | **Cesspool found**<br>No |

| Record drawing | |
|---|---|
| **Drawing attached**<br>Yes | |
| Show the house, tank, pump chamber, soil treatment area, and any well, with distances. | |