Connecticut wood-destroying insect field notes

Field worksheet

Inspection order	
Property address 63 Mountain Road, West Hartford, CT 06107	
Client Nina Patel	**Inspection date** November 10, 2026
Inspecting company Farmington Valley Pest Services	**Inspector** Graham Pierce
Structures included House and detached garage	

Visible findings and limits
Evidence and location Old insect channels at the cellar window trim. Activity not confirmed.
Areas not inspected and why Storage blocks the back panel of the detached garage.
Conditions to note Wet soil below cellar window

Handoff	
Photos and diagram Photos 04 and 05 show the trim and a dated service sticker.	
Report requested Buyer’s lender WDI report	**Inspector sign-off** Graham Pierce
Transfer the findings to the form your client or lender asks for. Keep these notes with the job.	