CONTROL SERVICE REINSPECTION REPORT

Street address	City	State / ZIP	Date of inspection	Pages
715 Kainalu Drive	Kailua	HI 96734	09/14/2026	1

LT

Lanakila Termite & Pest Control, Inc.

1830 Dillingham Boulevard
Honolulu, HI 96819
(808) 555-0142
office@lanakilapest.com

PCO no. PCO-1514
Contract no. CS-26-0041
Report no. CS-26-0041-3

Client	Mailing address
Lisa Hirano	715 Kainalu Drive, Kailua, HI 96734

Control service agreement and original report

☑ Subterranean ☐ Drywood

Agreement date	Expiration date	Original PC-9 inspection date	PC-9 signed by
03/16/2026	03/15/2027	03/02/2026	Glenn Takushi, PCO-1287

This inspection

Inspected by	License no.	Portions inspected
Kawika Mendoza	PCFR-4182	House, attached garage, and all 16 stations around the outside

Findings

☐ No change from original report ☑ Changes written below

Changes from the original report, and where

Live Formosan subterranean termites feeding in station 7, makai side by the lanai, about half the bait eaten. The mud tubes at the garage slab joint on the 03/02/2026 PC-9 are dry and broken, with no live termites. No new tubes or damage on the house or garage.

Areas not inspected, and why

Garage back wall behind stored boxes and shelving. Interior walls behind finished drywall.

Conducive conditions

Sprinkler wets the slab edge by station 7. Advised turning the head away from the house.

Bait or monitoring stations

Stations in place	Stations checked	Termite activity found in	Bait added or replaced in
16	16	Station 7	Station 7

Treatment this visit

☐ None ☑ Treated

Product	EPA Reg. No.	Amount, and where
Recruit HD termite bait (noviflumuron 0.5%)	62719-608	1 bait device in station 7, termites tapped into the new device

Charge for this treatment ☑ No charge under the agreement ☐ Billed separately — **Amount**

Signature of inspector	Date	Next inspection due
Kawika Mendoza	09/14/2026	12/14/2026

Signature of client	Printed name	Date
Lisa Hirano	Lisa Hirano	09/14/2026

HRS 460J-19(c): "A licensee is not required to issue a report as outlined in paragraphs (1) to (6) after each control service inspection. If after control service inspection, no modification of the original written inspection report is made in writing, then it will be assumed that conditions are as originally reported."

HAR 16-94-72(b): "The pest control operator shall keep the original inspection report and any subsequent control service reports for a period of not less than two years after completion of the control service agreement. The records shall be made available to a representative of the board during normal state business hours."