# Iowa wood-destroying insect field notes

Field worksheet

| Inspection order | |
|---|---|
| **Property address**<br>1347 Sugar Creek Lane, North Liberty, IA 52317 | |
| **Client**<br>Molly Jensen | **Inspection date**<br>November 4, 2026 |
| **Inspecting company**<br>Clear Creek Pest Services | **Inspector**<br>Noah Mercer |
| **Structures included**<br>House and attached garage | |

| Visible findings and limits |
|---|
| **Evidence and location**<br>No visible insect evidence on the open east rim joist. |
| **Areas not inspected and why**<br>Finished wall prevents a view of the south crawlspace rim. |
| **Conditions to note**<br>Rear deck post is close to grade |

| Handoff | |
|---|---|
| **Photos and diagram**<br>Photos 01–04 cover the open east rim and crawl entry. | |
| **Report requested**<br>WDI report for refinance | **Inspector sign-off**<br>Noah Mercer |
| Transfer the findings to the form your client or lender asks for. Keep these notes with the job. | |