Kansas wood-destroying insect field notes

Field worksheet

Inspection order	
Property address 1419 Indiana Street, Lawrence, KS 66044	
Client Clara Reed	**Inspection date** November 9, 2026
Inspecting company Kaw Valley Pest Services	**Inspector** Evan Cook
Structures included Dwelling and detached garage	

Visible findings and limits
Evidence and location Old shelter tubes at north foundation by water entry. No live insects seen.
Areas not inspected and why Finished wall covers the west basement sill.
Conditions to note Untreated wood at the base of the west porch

Handoff	
Photos and diagram Sketch L-09 marks the foundation entry. Photos 02 and 03 tied to the sketch.	
Report requested Purchase lender WDI report	**Inspector sign-off** Evan Cook
Transfer the findings to the form your client or lender asks for. Keep these notes with the job.	