Kentucky termite inspection field sheet

Notes for the NPMA-33

Order and property

Property address
418 Meadowlark Drive, Bowling Green, KY 42104

Ordered by	Inspection date
Rachel Whitaker, buyer's agent	October 14, 2026

Structures inspected
House, attached carport, and rear deck

Company and inspector

Company name
Barren River Pest and Termite

Company license number	Inspector name
2219	Caleb Ashby

Inspector KDA license
7A-50318

Findings

Location	Evidence seen	Insect	Photo
North crawl space pier	Active mud tubes	Subterranean termite	P-03
Rear sill near bath	Damaged wood, probed soft	Subterranean termite	P-05
Deck fascia, east end	Round holes and staining	Carpenter bee	P-09

Obstructions and inaccessible areas

Area	What blocked it	Return visit?
Crawl space under addition	18 in. clearance, ductwork	Yes
Finished basement walls	Paneling	No

Before you sign

Previous treatment papers
Seller has a 2019 graph from another company

Treatment recommended	Report sent to
Yes, subterranean termites	Buyer, agent, and lender

Visible evidence only. This is not a structural damage report.