Kentucky termite treatment graph

302 KAR 26:090

Job	
Owner Harold and Denise Whitfield	**Property address** 117 Glenns Creek Road, Frankfort, KY 40601
Treatment date April 21, 2026	**Applicator and license** Luis Ortega, 7A-29854
Company Capital City Termite and Pest	

Structure	
Type of structure One story ranch house with attached garage	**Foundation** Block crawl space, slab garage
Length 64 ft	**Width** 30 ft

Graph

A	B	C	D	E	F	G	H	I	J
	T	T	T	T	T	T	T	T	
T				X					T
T				D					T
T			House						T
T						H	H	H	T
T						H	Garage	H	T
T						H	H	H	T
	T	T	Front	T	T	T	T	T	

Outline the structure. Mark activity, damage, and every treatment, including partial areas.

Legend	
Activity mark X = live termites or active tubes	**Damage mark** D = damaged wood
Treatment methods T = trench and rod, 0.06% Termidor SC. H = slab drill holes.	

Owner copy	
Given to owner Handed to Denise Whitfield, April 21, 2026	**Application record** Ticket 4471