AEROBIC TREATMENT UNIT INSPECTION AND SERVICE REPORT

A template for the report LAC 51:XIII.725.M names, the "Individual Mechanical Plant Initial Warranty Inspection/Service Report." LDH posts no blank for it. This is not an LDH form.

Parish health unit	Permit # (LHS-47)	Date of this visit	Date of installation
Livingston Parish Health Unit	32-2012-0614	08/17/2026	05/22/2012
Name of property owner	**Physical address**	**City/State/Zip Code**	
Patrick and Denise Rivet	28415 Buddy Ellis Road	Denham Springs, LA 70726	
Treatment plant sewage I.D. tag #	**Plant capacity (gpd)**	**Manufacturer**	**Plant model**
118204	500	Norweco, Inc.	Singulair 960-500
Aerator serial #	**Aerator model**	**Discharge method**	**Disinfection**
206C-1204-7718	Model 206C	Spray, 3 heads	Tablet chlorinator

1 Visit

☐ Initial two-year service policy visit: ☐ 1 ☐ 2 ☐ 3 ☐ 4

☑ Extended service contract visit ☐ Certified homeowner's six-month check ☐ Service call or repair

Maintenance contract date(s)	through	Time arrived	Time left
03/01/2026	02/28/2027	9:10 a.m.	10:05 a.m.

2 Distance of system from

Private well	Public well	Pressurized water lines	Property boundary
None on site	None within 300 ft	14 ft	18 ft

3 Six-month inspection and service

LAC 51:XIII.725.F.2(d): components are "inspected, adjusted, and serviced"

Component	OK	Serviced	Repair	What was found and done
Power, breaker, and GFCI	X			Breaker on. GFCI tested and reset.
Control panel and timer settings	X			Spray timer set for 1:00 to 4:00 a.m.
Alarm, sound and light tested	X			Horn and light work when the float is lifted.
Aerator and its intake filter		X		Running quietly. Intake filter cleaned.
Air lines and diffusers	X			Even rolling across the aeration chamber.
Pretreatment (trash) tank	X			Scum 2 in. Sludge 9 in. Inlet clear.
Aeration chamber	X			Light brown mixed liquor, little foam.
Clarifier and sludge return	X			Clear on top. No floating solids.
Chlorinator and tablets		X		One tablet left. Added three.
Pump tank, pump, and floats	X			Pump starts and stops on its floats.
Spray heads or other discharge			X	Heads 1 and 2 pop up and turn. Head 3 cap cracked.
Lids, risers, and seals	X			Lids seated and screwed down.

4 Effluent quality

LAC 51:XIII.725.F.2(d): "a visual assessment of color, turbidity, and scum overflow, and an olfactory assessment for odor"

Check	What was seen	Pass	Fail
Color	Clear	X	
Turbidity	Slight haze	X	
Scum overflow	None	X	
Odor	None, faint chlorine	X	
Total chlorine residual (ppm), if chlorinated	1.0 ppm (DPD test kit)	X	

5 Pump-out

Sludge depth, pretreatment tank	Pumping needed	System pumped out	Hauler company
9 in.	Not yet	No. Last pumped 03/2023	

6 Problems not fixed at this visit

The owner gets each one in writing, with an estimated date of correction.

No.	Problem found	Estimated date of correction
1	Spray head 3 cap cracked. It throws a narrow stream toward the back fence. Head capped off until the new one comes in.	08/24/2026, new head ordered
2		
3		
4		
5		

7 Notes

Home under contract to sell. The extended contract can move to the new owners at closing.

Next six-month visit due by 02/2027, before the contract renews.

8 Filing

LAC 51:XIII.725.M.1: The "Individual Mechanical Plant Initial Warranty Inspection/Service Report" must be submitted to the state health officer after each warranty/maintenance inspection is completed by the maintenance provider, and will become part of the permanent record for each system.

- [x] Copy given to the owner
- [x] Sent to the state health officer (parish health unit) on 08/18/2026
- [ ] Extended service contract negotiated. State health officer notified on _____

9 Maintenance provider

I inspected and serviced this system on the date above. This report records what I checked, what I found, and what I did.

Licensed maintenance provider	LDH license #	Company	Phone
Curtis Bourgeois	0418	Florida Parishes Aerobic Service, LLC	(225) 555-0129

Curtis Bourgeois

Signature of licensed maintenance provider — Date: 08/17/2026

Denise Rivet

Owner or occupant who received a copy — Date: 08/17/2026