New Mexico wood-destroying insect field notes

Field worksheet

Inspection order	
Property address 1614 Agua Fria Street, Santa Fe, NM 87505	
Client Diana Lucero	**Inspection date** November 16, 2026
Inspecting company High Desert Pest Services	**Inspector** Jonah Romero
Structures included Dwelling and rear casita	

Visible findings and limits
Evidence and location Old tunnels in the exposed porch support on the west side.
Areas not inspected and why Stucco obscures the junction at the east foundation.
Conditions to note Porch support meets damp soil by drain outlet

Handoff	
Photos and diagram Sketch SF-16 marks porch support P1. Photo 04 shows the old tunnels.	
Report requested Lender WDI report	**Inspector sign-off** Jonah Romero
Transfer the findings to the form your client or lender asks for. Keep these notes with the job.	