New York septic system inspection report

County transfer inspection • Seneca County Local Law #7 of 2021

Property	
Property address 3418 Lower Lake Road, Seneca Falls, NY 13148	
Owner Estate of Carol Brandt	**Buyer** Michael and Jen Ostrowski
Inspection date September 28, 2026	**Occupied** No, vacant since July

Inspector	
Inspector and certification Dale Hutchins, Seneca County certified inspector	
Company and phone Cayuga Septic Inspections, (315) 555-0176	

System	
System type Septic tank with gravity trench field	
Bedrooms 3	**Tank size** 1,000 gal concrete
Last pumped Not since 2021. Pumping booked for October 2.	

Hydraulic load	
Gallons added 330	**Hours** 6
Dye placed in Upstairs toilet and kitchen sink	

New York septic system inspection report (continued)

County transfer inspection • Seneca County Local Law #7 of 2021

Components	
Component	**Condition**
Building sewer	Cleanout found, flows freely
Tank inlet baffle	Intact
Tank outlet baffle	Intact, effluent filter clean
Distribution box	Level, all outlets clear
Trench field, 3 laterals	No dye or wet spots after load
Shoreline below field	No dye seen

Result
Outcome Pass
Pump-out proof Receipt to follow after October 2 pumping
Sent to health department September 30, 2026