Ohio NPMA-33 field sheet

Ohio Admin. Code 901:5-11-13

Section 1: business and property

Business and phone
Scioto Valley Pest Control, 614-555-0187

Business license	Inspection date
51247	November 18, 2026

Property address
4127 Leap Road, Hilliard, OH 43026

Inspector and license
Marcus Hale, license 129874

Structures inspected
House and attached garage. Detached shed not ordered.

Section 2: evidence found

Box	Insect or evidence	Exact location
B(2)	Old subterranean termite mud tubes	North foundation wall at sill plate
B(3)	Galleries in floor joist	Second joist east of basement stairs
B(2)	Carpenter ant frass	Rear porch band board

Section 3: treatment call

Treatment recommended
No treatment recommended

Evidence relied on
Tubes dry and broken, no live termites. Drill holes in garage slab and May 2023 treatment sticker.

Section 4: obstructed areas

Areas checked
Finished basement walls, north and east; crawl space under family room

What blocked view
Drywall and paneling. Crawl space hatch sealed under carpet.

Panels that come off with screwdrivers, pliers, or wrenches do not count as obstructions.

Ohio NPMA-33 field sheet (continued)

Ohio Admin. Code 901:5-11-13

Section 5: previous treatment
Previous treatment seen Yes. Liquid treatment, sticker dated May 2023.
Where seen Garage slab along house wall; sticker on electric panel
Attachments Page 2: basement diagram with tube locations

Deadlines	
Signed on November 20, 2026	**Copy to office** November 20, 2026
Sign within 5 business days. Office copy within 10 days. Business keeps it 3 years.	