Ohio termite treatment and bait station record

Ohio Admin. Code 901:5-11-10(A)(1), (3), and (4)

Job

Customer name
Linda Ferraro

Property address
2659 Wellesley Drive, Columbus, OH 43221

Applicator	Servicepersons
Marcus Hale, license 129874	Jordan Pace

Footprint drawing

Drawing date
April 6, 2026, before treatment

Footprint size	Linear feet
46 ft by 28 ft	148

Footer depths
Front 4 ft, sides 6 ft, rear 6 ft

Made before any application. Footer depths on all exterior walls for liquid jobs.

Liquid treatment

Trade name	EPA Reg. No.	Dilution	Total gallons	Where and how
Termidor SC	7969-210	0.06%	236	Trench and rod, full perimeter
Termidor SC	7969-210	0.06%	18	Drilled garage slab at house wall

Time of application

Start time	Finish time
8:40 a.m.	1:15 p.m.

Ohio termite treatment and bait station record (continued)

Ohio Admin. Code 901:5-11-10(A)(1), (3), and (4)

Bait stations

Visit date	Bait and EPA No.	Stations	Active stations
April 6, 2026	Monitoring only	12 installed	None
July 14, 2026	Monitoring only	12 checked	None
October 19, 2026	Recruit HD, 62719-608	12 checked	Station 7

Office copy

Sent to office
April 7, 2026

Ohio termite footprint drawing

Ohio Admin. Code 901:5-11-10(A)(3)

Drawing details	
Property shown 2659 Wellesley Drive, Columbus, OH 43221	
Drawing ID LF-0406	**North arrow** Top of grid
Scale 1 square equals 6 ft	

Footprint grid

A	B	C	D	E	F	G	H	I
				N				
	1	T	T	T	T	T	2	
	T						T	
	12		House			Garage	D	3
	T						D	
	11						T	4
	T	10	T	Stoop	T	7	T	
		9		8		6	5	

Show linear dimensions, footer depths, and numbered stations.

Legend

Marks used
T = trench, D = drilled slab, numbers = bait stations

Areas not treated
Front stoop slab, no access to soil