# Pennsylvania WDI inspection field sheet

For the NPMA-33

| Job details | |
|---|---|
| **Company and phone**<br>Conestoga Pest Management, 717-555-0172 | |
| **Inspector**<br>Eric Zimmerman | **Category 12 cert**<br>Yes, cert. 284716 |
| **Property address**<br>418 Marietta Avenue, Lancaster, PA 17603 | |
| **Inspection date**<br>September 9, 2026 | **Ordered by**<br>Hannah Brubaker, buyer |

| Buildings inspected |
|---|
| **Buildings included**<br>Dwelling and detached one-car garage |
| **Buildings not included**<br>Garden shed |

**Findings**

| Insect | Live, evidence, or damage | Location |
|---|---|---|
| Subterranean termites | Live | Mud tubes on stone foundation, front left corner |
| Carpenter ants | Evidence (frass) | Garage sill plate, east wall |
| Powderpost beetles | Damage, inactive | Basement joists under kitchen |
| | | |
| | | |
| | | |

| Not visible |
|---|
| **Obstructed areas**<br>Finished rear basement room; front porch underside |
| **Why**<br>Drywall and paneling; porch skirting nailed shut |

# Pennsylvania WDI inspection field sheet (continued)

For the NPMA-33

| Treatment |
| --- |
| **Prior treatment seen**<br>None. No drill holes or service stickers. |
| **Treatment recommended**<br>Yes. Live subterranean termites, no prior treatment. |

| Report sent | |
| --- | --- |
| **Signed on**<br>September 9, 2026 | **Sent to**<br>Buyer, buyer’s agent, lender |