Utah wood-destroying insect field notes

Field worksheet

Inspection order	
Property address 1148 South 1740 East, St. George, UT 84790	
Client Nathan Ortega	**Inspection date** November 13, 2026
Inspecting company Red Cliffs Pest Services	**Inspector** Maren Fielding
Structures included House and attached carport	

Visible findings and limits
Evidence and location Dry channels at the old carport trim. No active insects seen there.
Areas not inspected and why Stucco and paving hide the lower foundation along the east wall.
Conditions to note Wood trim touches soil by side gate

Handoff	
Photos and diagram Photo 03 at carport post C2. Sketch SG-13 shows the east wall limit.	
Report requested Washington County VA lender order	**Inspector sign-off** Maren Fielding
Transfer the findings to the form your client or lender asks for. Keep these notes with the job.	