Wisconsin wood-destroying insect field notes

Field worksheet

Inspection order	
Property address 4218 Hammersley Road, Madison, WI 53711	
Client Lena Morales	**Inspection date** November 12, 2026
Inspecting company Driftless Pest Services	**Inspector** Caleb Ritter
Structures included House and attached garage	

Visible findings and limits
Evidence and location Dry mud tubes at the southwest sill. No live insects seen there.
Areas not inspected and why Foam covers the sill at the northwest corner.
Conditions to note Soil touches the rear stair stringer

Handoff	
Photos and diagram Photo 03 and sketch mark the sill at the west wall.	
Report requested Lender WDI report	**Inspector sign-off** Caleb Ritter
Transfer the findings to the form your client or lender asks for. Keep these notes with the job.	