Wisconsin POWTS maintenance worksheet

Septage service and field notes

Property file	
Property address 7386 County Road P, Cross Plains, WI 53528	
Owner Mara Dwyer	**Permit or file number** Dane 2012-0621
Provider Coulee Septic Service	**Visit** November 5, 2026

System and service	
System type and field location Conventional tank and trenches, north lawn.	
Service performed Tank pumped	**Volume removed** 1,000 gal
Field and cover observations No ponding seen. Both lids secured.	
Parts needing repair Outlet filter cleaned; no repair noted.	

Follow-up	
Next service check Per county schedule	**Local record** Dane County maintenance record
Provider signature Jules Larson	